

Important notice affecting the warranty of this Starter Motor



Please read!

Many starting faults are mis-diagnosed, leading to the unnecessary change of starter motors. Faults that do not originate from the starter motor, or cause the starter motor to fail, will result in the subsequent failure of any replacement starter motor. Therefore, please examine your old starter motor for the following:

- Red or blue burn marks around the pinion teeth or armature shaft.
- Evidence of a burnt out motor. This is obvious from a burning smell from inside the starter motor, or at the rear end from the brush box.

From our experience, the above problems are usually caused by a faulty ignition switch or faulty start relay – if in doubt, please replace!

- Worn pinion teeth – this would indicate an incorrect fitment or existing damage to the ring gear.
- Excessive oil or water ingress.

If your old starter motor exhibits any of the above, a replacement starter motor will not solve the problem! Our replacement starter motor will fail on the vehicle for exactly the same reasons, and the unit will not be covered under warranty.